

MEBT MEETING AGENDA

October 25, 2001

Mechanical Systems Update

- 1. Assembly Status
 - Raft 1 Assembly (photo)
 - Fiducialization (results)
 - Rafts 2 (photo)
- 2. Design Status (MEBT)
 - PM5 vacuum manifold (<u>image</u>)
 - Raft assembly drawings
 - Water system (<u>views</u>)
 - Quad power lead routing
 - Quad Electrical Covers

Electrical Systems Update

- 1. Low Level RF
- 2. Rebuncher System
- 3. Beam Diagnostics

System Integration / Installation

1. Installation of MEBT frame

Upcoming Tasks and Milestones


• Rebuncher Cavity #2-4 Received

6/30/01

Profile Monitor all complete


7/31/01

Next Meeting: Thursday, 11/8/01, 10 AM



Raft 1 Quad Locational Deviations (x&y)

Deviation values: the difference between the measured position of each fiducial surface and its nominal position. Measurements taken 10/23-10/24/01.



Quad Number (Left/Right)

Raft 3 Quad Locational Deviations (x&y)

Deviation values: the difference between the measured position of each fiducial surface and its nominal position. Measurements taken 10/4-10/8/01.

